

8113 West Sherman Street Tel: 602.233.9166 Tolleson, AZ 85353-4025 Fax: 623.936.9164

November 7, 2003

Mr. Gerald Thompson Environmental Assistant Alaskan Copper Works P. O. Box 3546 Seattle, WA 98124-3546

Dear Mr. Thompson:

Enclosed is the appropriate copy of your company's Hazardous Waste Manifest resulting from the transfer of recyclable materials to World Resources Company.

Please note that in accordance with 40 CFR §262.40, this copy of the manifest must be retained as a record for at least three (3) years from the date the waste was accepted by the initial transporter.

If you have any questions, please feel free to give us a call.

Sincerely,

World Resources Company

Manifest Coordinator

**Enclosures** 

WORLD RESOURCES 11:58AM 11/05/2003 GROSS 1225 1b TARE 77 1b NET 1148 1b WORLD RESOURCES 11:59AM 11/05/2003 GROSS 1315 1b TARE 77 1b NET 1238 1b ACCUM 2386 16 11/05/2003 12:00PM

Plea	as print or type. (Form designed for use on e					Form Approved.	OMB No. 2	050-0039.			
	UNIFORM HAZARDOUS	1. Generator's US EPA	ID No. Mani		2 P	age 1 Info	mation in	the shaded areas			
	WASTE MANIFEST	W.A.D.9.8.0.7	385460	iment No. 2 A A 9	of	_   in me		d by Federal law.			
	3. Generator's Name and Mailing Addr		<u> </u>	<u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>		ate Manifest	Jooumon	t Number			
Ш	Alaskan Copper Works	Alaskan Copper Works									
	P.O. Box 3546, Seatt	Alaskan Copper Works P.O. Box 3546, Seattle, WA 98124  B. State Generator's II									
	4. Generator's Phone ( 206 ) 3	ማስሳ ሳባሳ ስላማለ									
	5. Transporter 1 Company Name	6.	US EPA ID Numbe								
	15. Transporter I Company Name	ate Transpor	_ ·								
11	PHILIPTRANPORTATION	CHEMEDIA CON CHI			*	ansporter's P	hone 9	300-321-1636			
Ш	7. Transporter 2 Company Name	11 15 15 15 15 15 15 15 15 15 15 15 15 1	US EPA ID Numbe	er		ate Transport		\$4. 48775A. 4053			
11					4	ansporter's P					
	9. Designated Facility Name and Site A	Designated Facility Name and Site Address 10. US EPA ID Number G. State Facility's ID									
	World Resources Compa	$\mathbf{n}\mathbf{y} = \{(\lambda_{i,j}^{\lambda})_{i,j=1}^{\lambda}, \lambda_{i,j}^{\lambda}\}$			Nas.		See all				
	8113 West Sherman Str					acility's Phone	800_	972-1955			
	Tolleson, Arizona 853	53-4025 A.Z.	D_9_8_0_7_3_5	5,5,0,0	1000		000-	912-1900			
П	11. US DOT Description (Including Prop		on and ID Number	12. Conta	iners	13. Total	14.				
G	HM	ei Snipping Name, nazaru Cia	ss and iD Number)	No.	Type	Quantity	Unit Wt/Vol	Waste No.			
E N	a. DO Unanyana		_					Value and the second			
Ε		waste, solid, n.o.	<b>B.</b> ,				_	F006			
R	(F006), 9, NA3	0077, 111		ØØ 2	CF	1255	P او				
	b.					<del></del>	4	NESASSA SEEN ATTEN			
				ļ							
3	,										
	C				<u> </u>		7.1				
					ı						
-	d. 3,7 3,7 4,7 4,7 4,7			1				75 27.27.05 7.27.0 1.46.49.45.07.77.11			
					ļ						
				114							
	15. Special Handling Instructions and A 24 Hour Emergency Respo (Emergency call, pager #	nse: 1-800-424-930 206-648-8423) _				EC compai	ny cod	le "WORR")			
ŀ	16. GENERATOR'S CERTIFICATION: I hereby		ignment are fully and one	rotolu deceri			· · · · · · · · · · · · · · · · · · ·				
	proper shipping name and are classified, pa	acked, marked, and labeled, and are i	n all respects in proper co	ndition for tra	ueu abov Insport b	y highway	·				
	according to applicable international and na										
	If I am a large quantity generator, I certife economically practicable and that I have	ly that I have a program in place to selected the practicable method of	o reduce the volume and f treatment, storage, or o	l toxicity of v disposal curri	vaste ge ently ava	nerated to the dailable to me wi	iegree I ha nich minim	ave determined to be			
	future threat to human health and the en	vironment; OR, if I am a small qua	ntity generator, I have m.	ade a good	faith effo	ort to minimize i	ny waste g	generation and select			
	the best waste management method that is	available to me and that I can afford	<del></del>								
7	Printed/Typed Name		Signature	2			· / · · · · ·	Month Day Year			
Ц	GERAID Thompson		Xx JOH	2				102903			
, L	17. Transporter 1 Acknowledgement of	f Receipt of Materials	$\sim$								
	Printed/Typed Name		Signature			11.		Month Day Year			
šĿ	IT (ARROLL		Jalan	oll				102703			
<u>S</u>	18. Transporter 2 Acknowledgement of	f Receipt of Materials									
	Printed/Typed Name		Signature		1			Month Day Year			
<u>I</u>											
	19. Discrepancy Indication Space										
. [2	20. Facility Owner or Operator: Certific	ation of receipt of hazardous r					Item 19.				
, [	Printed/Typed Name	01 -	Signature		, /	2/		Month Day Year			
$\perp$	Hrmando	Chavez	Signature Com	mile	9- L	nava		1110503			

Style CF 17 LABEL ASTER ® (800) 621-5808 www.labelmaster.com

EPA Form 8700-22 (Rev. 9-88) Previous editions are obsolete.

ORIGINAL-RETURN TO GENERATOR



Plea	se print or type. (Form designed for use on elite (	12-nitch) typewriter )			_	orm Approved. C	ME No 2	050.0020
Ā	UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPAI	Docu	iment No.	2. Pag	ge 1 Inform	nation in	the shaded areas by Federal law.
	3. Generator's Name and Mailing Address Alaskan Copper Horks P.O. Box 3546, Seattle, 4. Generator's Phone (206)				A. Stat	te Manifest Do		t Number
	Fransporter 1 Company Name PHILIPTRANIORTATIONA		te Transporter nsporter's Pho		200-321-103			
	7. Transporter 2 Company Name	E. Stat	te Transporter nsporter's Pho	's ID				
	Designated Facility Name and Site Address World Resources Company 8113 West Sherman Street Tolleson, Arizona 85353-		US EPA ID Number		G. Sta H. Fac	te Facility's ID		972-1955
	11. US DOT Description (Including Proper S			12. Conta		13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
ENERA	RQ, Hazardous was (F006), 9, NA307		S., s			82554		PO06
	D							
	<b>1</b>	78 PAIL						
		decimandation that were residue green a recommengy was	n i un indeputation proprieta in page security pro i i	entente Provincia de la compa		and the second second second	A se Arge	
	Additional Descriptions for Materials Lists     electrical rectude of contracts     transpowers 8.0.0 ESS (	i elemento proceso de la composición d La composición de la	Troiwswer one wet	akings on	g satu,	ions, garnaut	tourran	s Listed Above
	24 Hour Emergency Response  (Emergency call pager # 20	re that the contents of this cons marked, and labeled, and are in government regulations. It I have a program in place to teled the practicable method of	ignment are fully and according all respects in proper coording to reduce the volume and treatment, storage, or or	urately descripted distribution for tra	bed above insport by i	by highway erated to the de able to me whic	gree 1 ha	ive determined to be zes the present and
	Printed/Typed Name			Summer of the second of the se	or one had a surface of the surface	Thinking Hy		Month Day Year
RAN	7. Transporter 1 Acknowledgement of Rec Printed/Typed Name	ceipt of Materials	Signature					Month Day Year
TRANSPORTER	8. Transporter 2 Acknowledgement of Rec Printed/Typed Name	ceipt of Materials	Signature	*U				Month Day Year
1	9. Discrepancy Indication Space			-				
1 A(C) - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	Facility Owner or Operator: Certification     Printed/Typed Name	of receipt of hazardous n	naterials covered by	this manife	st except	t as noted in It	·	Month Day Year

Style CF 17 LABELIMASTER® (800) 621-5808 www.labelmaster.com

EPA Form 8700-22 (Rev. 9-88) Previous editions are obsolete.



**GENERATOR COPY** 










ISO 9001 & ISO 14001 Certified Recycling Facility



A copy of this Notice must be retained by the Generator for at least three (3) years, pursuant to U.S. EPA Regulation 40 CFR §268.7(a)(8). Moreover, the Generator should check the hazardous-waste regulations of his/her own State, inasmuch as, if there is a State analogue to the federal regulation, it may require a longer retention time, such as five (5) years. It should also be noted that the federal regulation--and, typically, State analogues as well-requires the retention period to be extended further in specified cases.

To:	WORLD RE	SOURCES COMPANY	8113 West Sherm	an Street, Tolleson AZ 85353-4025	_							
From:	COMPANY NA		COMPANY ADDRESS:		=							
	Alaskan Copper Works		P.O. Box 3546, Seattle, W	WA 98124								
MANIFEST 03004			DATE SHIPME									
The	This shipment of material is subject to the land disposal restrictions of 40 CFR Part 268. The applicable land disposal restriction information, provided in accordance with 40 CFR §268.7(a)(2), is as shown in this table ■											
		EPA Material Number F006	Treatability Group non-wastewater	CFR Reference for Treatment Standards 40 CFR §268.40								
SIGN	NATURE:	Dlin	TIT	TLE: Enviro. TECH								
NAME P	RINTED:	ERAD A. Tho.	mpson DA	ATE: 10-29-03								

## Instructions for Completion of this Land Disposal Restriction Notice [LDRN]

This LDRN has been prepared based on a listed material--F006--as the primary designation of the material. This designation is based on information furnished by the Generator of the material. While it is believed to be accurate, it is the Generator's responsibility to determine whether his/her material is restricted from land disposal, and to correctly complete the LDR Notice [as stated in 40 CFR §268.7(a)(2)].

An F006 designation on the LDRN includes the following constituents: cadmium [D006], chromium [D007], lead [D008], silver [D011], cyanide, and nickel. However, the designation does not include arsenic [D004], barium [D005], mercury [D009], or selenium [D010]. If your F006 material contains any of those four constituents not included in the F006 designation, then use the following instructions.

In determining the need for any additional entries on the LDRN for the F006 material, the levels of arsenic, barium, mercury and selenium must be examined to determine if the levels equal or exceed the threshold concentrations of constituents for the Toxicity Characteristic limit as identified in 40 CFR §261.24 (Table 1), as shown in the left-hand column of the table below [as stated in 40 CFR §268.9].

If (after testing or based upon the generator's knowledge of the material) each metal level does not equal the Toxicity Characteristic level shown below, then no additional entry is required on the LDR Notice. If the level is known to be or determined to be equal to or above the limit shown below for any of these metals, then the appropriate information corresponding to that individual metal (in the right-hand column below) must be added to the LDR Notice.

¥	1	EINFORMATION CHARACTERISTIC	APPROPRIATE ENTRY ON LDR NOTICE					
	Metal	Concentration Level	EPA Material Number	Treatability Group	CFR Reference for Treatment Standards			
:	ARSENIC	5.0 mg/l	D004	non-wastewater	40 CFR §268.40			
	BARIUM	100 mg/l	D005	non-wastewater	40 CFR §268.40			
[	MERCURY	.02 mg/l	D009	non-wastewater	40 CFR §268.40			
ĺ	SELENIUM	1.0 mg/l	D010	non-wastewater	40 CFR §268.40			

**FOOG GENERATORS** 

#### MATERIAL IDENTIFICATION

DOT BASIC SHIPPING DESCRIPTION AND TECHNICAL NAME: Hazardous waste, solid, n.o.s., (F006), 9, NA3077, III



## TAKEN FROM GUIDE 171 OF THE NORTH AMERICAN EMERGENCY RESPONSE GUIDEBOOK

(Underlined text applies directly to the material listed above)

#### POTENTIAL HAZARDS

#### FIRE OR EXPLOSION

- 1. Some may burn, but none ignite readily.
- Some may polymerize (P) explosively when heated or involved in a fire
- 3. Containers may explode when neated. 4. Some may be transported hot.

- - 1.Inhalation of material may be harmful
  - Contact may cause burns to skin and eyes
  - 3.Innalation of Aspestos dust may have a damaging effect on the lungs.
  - Fire may produce irritating, corresive and/or toxic gases.
  - Runoff from fire control may cause pollution.

#### PUBLIC SAFETY

- 1. CALL CHEMTREC at 1-800-424-9300 FOR EMERGENCY ASSISTANCE (Use CHEMTREC Company Code "WORR") 2. Isolate, spill or leak area immediately for at least 10 to 25 meters (30-80 feet) in all directions.
- 2. Isolate spill or leak area immediately for at least 10 to
- 3. Keep unauthorized personnel away
- 4. Stay upwind.

#### PROTECTIVE CLOTHING

- 1. Wear positive pressure self-contained preathing apparatus (SCBA).
- 2. Structural firefighters' protective clothing will only provide limited protection.

#### **EVACUATION**

#### Fire

1.If tank, rail car or tank truck is involved in a fire, ISOLATE for 800 meters (1/2 mile) in all directions; also, consider initial evacuation for 800 meters (1/2 mile) in all directions.

#### FIRE

### **EMERGENCY RESPONSE**

#### Small Fires

1. Dry chemical CO2 water spray or regular foam

#### Large Fires:

- 1. Water spray, fog or regular foam
- 2. Move containers from fire area if you can do it without risk.
- 3. Do not scatter spilled material with high pressure water streams.
- Dike fire-control water for later disposal.

#### Fire Involving Tanks:

- 1.Cool containers with flooding quantities of water until well after fire is out.
- Withdraw immediately in case of rising sound from venting safety devices or discoloration of tank.
- 3.ALWAYS stay away from the ends of tanks

#### SPILL OR LEAK

- 1.Do not touch or walk through spilled material.
- 2.Stop leak if you can do it without risk 3.Prevent dust cloud.
- 4. Avoid inhalation of aspestos dust

#### Small Dry Spills

- With clean shove! place material into clean, dry container and cover loosely; move containers from spill area Small Spills
- Take up with sand or other noncombustible absorbent material and place into containers for later disposal. Large Spills
- Dike far ahead of liquid spill for later disposal.
   Cover powder spill with plastic sheet of tarb to minimize spreading.
- 3. Prevent entry into waterways, sewers, pasements or confined areas

#### FIRST AID

- 1. Move victim to fresh air
- 2.Call emergency medical care
- Apply artificial respiration if victim is not breathing
- Administer oxygen if breathing is difficult.
- 5. Remove and isolate contaminated clothing and shoes.
- In case of contact with substance, immediately flush skin or eyes with running water for at least 20 minutes

Ensure that medical personnel are aware of the material(s) involved, and take precautions to protect themselves.

Copyright 1994 World Resources Company

Recycled Paper 02/09/2000

# **Material Safety Data Sheet**

F006 Recyclable Material (Filter Cake)

Recycler's Facility Name and Site Address:

### World Resources Company

8113 West Sherman Street Tolleson, Arizona 85353-4025 602/233-9166 Fax: 623/936-9164 January 2002 DLS

Call CHEMTREC only in the event of emergencies during shipping that involve a spill, leak, fire, or accident (all calls are recorded).

For emergencies during shipping in the US or Canada, day or night, call: CHEMTREC 800/424-9300

(Use CHEMTREC Company Code "WORR".) For calls from other countries, call COLLECT: 703/527-3887

Section 1

EPA Waste Classification: F006

Generic Name: Electroplating/Metal-Finishing Waste-

water Treatment Sludge

Chemical Family: Metallic (Hydroxide) Participates Synonym: Nonferrous Metal Hydroxide Filter Cake

ial Identification DOT Shipping Name: RQ, Hazardous waste solid, n.o.s., (F006)

DOT Hazard Class: 9; Packing Group: III.

DOT Identification Number: NA 3077 Guide 171 of The North American Emergency Response Guidebook applies.

Section 2				Hazardous Ingredients
Ingredient: Copper Hydroxide Nickel Hydroxide Calcium Hydroxide Diatomite Aluminum Hydroxide	CAS Number: 20427-59-2 12054-48-7 1305-62-0 61790-53-2 21645-51-2	Content%: 0-30 0-15 0-15 0-10 0-10	ACGIH-TLV:  1.0 mg(Cu)/m³ (dust)  1.0 mg(Ni)/m³ (dust)  5.0 mg(Ca)/m³ (dust)  10.0 mg/m³ (dust)  2.0 mg(Al)/m³ (dust)	Toxicology (rat, oral): LD-50 1,000 mg/kg LD-50 1,500 mg/kg LD-50 7,340 mg/kg LD-50 not determined LD-50 not determined

Section 3

Description: solid, clay-like, gray/green to brown, water content 30-80% Specific Gravity: 2.5 to 3.5 Solubility: insoluble in water.

Incompatible Reactivity: none known.

Vapor Pressure: insignificant. Stability: avoid contact with acids. Melting Point: above 1800°C

Polymerization: will not occur.

Density: 50-90 lbs./cu ft,

Physical and Reactivity Data Boiling Point: above 2600°C

pH: 7.0 to 10.0

Odor: nil.

Section 4

Flashpoint: nonflammable. Special Firefighting Procedures: none.

Product Decomposition (due to fire or explosion): none.

Oxidation: non-oxidizing.

Explosion Potential: non-explosive.

Fire and Explosion Data 0

n

**NFPA** Fire Diamond

Section 5

Listed Carcinogenic Components: nickel Toxicology: see Section 2. Route of Entry: inhalation and ingestion.

Section 6 Health Effects and First Aid

Innalation: Dust may irritate mucous membranes and upper respiratory tract. Remove to fresh air and treat symptoms. Ingestion: Rare. Induce vomiting and call a physician—but never induce vomiting or give a liquid to an unconscious person. Dust may irritate eyes. Wash with copious amounts of water for 15 minutes. If effects persist, call a physician. Eves:

Dust may irritate skin, causing forms of eczema. Wash with soap and water. Skin:

Long-Term: Long-term chronic over-exposure may affect the following target organs or body systems: blood; digestive; respiratory; lungs; liver;

kidnevs; and skin.

Comments: Special attention should be given to employees with anemia, restricted respiratory abilities, lung cancer, permanent kidney damage,

mental-sensitive skin, or skin lesions.

Section 7 Precautions for Safe Handling

Good personal and industrial hygiene should always be practiced. It is recommended that personal protective equipment (PPE) be Handling:

used by personnel who will come in contact with the material. The PPE should include eye protection, respirator and gloves. Storage:

Keep covered and avoid conditions where wind could cause dispersal. Do not eat, drink or smoke where material is handled, to avoid inhalation or ingestion. Store in a dry area under cover to protect from rain or snow.

Spills: Use cleaning procedures that avoid creating excessive dust. Vacuum when possible.

Package material and ship to World Resources Company at the address shown above.

Section 8

Section 9

**Control Measures** 

Generator's Verification

Respiratory Protection: NIOSH-MSHA approved respirators as required. Other Protective Equipment: coveralls are recommended but not required.

Eye Protection: safety glasses are recommended. Hand Protection: gloves are recommended.

This MSDS describes the recyclable material listed in the attached

Manifest Number:

**★**Signature ★

**†**Date **†** 

Alaskan Copper Works

P.O. Box 3546, Seattle, WA 98124

**★**Company Name and Address ★

206-382-8379

Telephone



# GENERAL INTERNAL PURCHASE REQUISITION

ITEM NO.	ACCT. NO.	QUAN- TITY	UNIT	DESCRIPTION & PART NUMBERS		UNIT PRICE	TOTAL LINE ITEM PRICE
	6-686	/	LOT	RECYCLE & TRANSPORT			****
				2EA F-006 Studge Bo	√€S		
<u> </u>							
	N 12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			2554 W			
						N 22	
	i. i. i. i.						
		N, t					
	1 1 N N N N N N N N N N N N N N N N N N						N.A.
		1.3.25	1. 1				
			:				
133	(Aux	2.5	1		MANTE		
	4 4		\				
					en skiba	V. 12	
	4,					1.14	<u> </u>
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	N.A.					
	\\\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.		24		10 10 10 10 10 10 10 10 10 10 10 10 10 1		
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		N. J.			· ·	
			, A		and the N		
	No. 2		4.				
	4.5.553	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
REQUE	STED BY			DATE / APPROVED BY		DA	TE
	X.14(			TO BE FILLED IN BY PURCH	HASING DEP	2 1/4	1/25/03
	HERE FOR RET	URN OF YEL	LOW COP	P.O. NUMBER	1193	1030	
	RY NEEDED	ВУ		VENDORA DIEL Ó	R	) C ( r n l	see B
	O ADDRESS		v. Pôr	CONTACT	TELEP	HONE	
	STED/ / \	rell F	o esoune		SHIPV	IA \/ 1	and the second



# GENERAL INTERNAL PURCHASE REQUISITION

ITEM NO.	ACCT. NO.	QUAN- TITY	UNIT	DESCRIPTI	ON & PART NUMBERS	UI PR	NIT IICE	TOTAL LINE ITEM PRICE			
1	16-686	1	207	Precicle & -	TRANSPORT						
				2EA F-006	Transport Studge Boxes	3					
				G.							
	AND			25	54 WT						
		and the second									
	410 000 200					and the second second					
				The second secon				And an artist of the second of			
	10 Big 2.52							and the second second second			
						and the second s		A Control of the Cont			
	- Canal										
-	<u> </u>										
REQUE	STED BY	5 18 miles		DATE / 10/28/03	APPROVED BY	7-2-2:	DATE //	25/03_			
HERE FOR RETURN OF YELLOW COPY PURPOSE OR USE					TO BE FILLED IN BY PURCHASING DEPT.  P.O. NUMBER 1192030						
	ERY NEEDED	BY			VENDORADRIA Rescuerces Co						
	O ADDRESS	10 m 10 m	<del></del> )		CONTACT TELEPHONE NO.						
VENDO	STED ()C Bev 7/96	meld sk	<u>esam</u>	es G	DELIVERY PROMISED	SHIP VIA	<b>V</b> 1	and the second s			